




















KMG/KGS/KC/KN




A1  X2	A2  X2	A3  X4	A4  X2	A4-1  X2	A5  X2
A6  ST4*10=4 X8	A7  X1	A7-1  X1	A8  X4	A9  X2	A10  X2
A11  X4	A12  X8	A13  6-7 N *2  5-6 N *2 X4	A14  ST4*30=8 X8	A15  ST4*30=14 X6	
A16  ST4*6=12 X12	A17  ST4*10=6 X6	A18  X12	A19  X6	A20  X1	A20-1  X1
A21  X1	A21-1  X1	A22  X14	A23  X4	A24  X1	A25  X1






2





3









6



7












8







9


KMG/KGS/KC/KN+MG/GS/C/N








A1  X1	A2  X1	A3  X2	A4  X2	A5  X1
A6  X1	A7  X1	A8  X2	A9  X2	A10  X4
A11 ST4*30=8  X8	A12 ST4*6=2  X2	A13 ST4*10=3  X3	A14  X3	A15 ST4*10=2  X2
A16  X1	A17  X1	A18  X1	A19 ST4*30=4  X4	A20  X4


















A1  X1	A2  X1	A3  X2	A4  X8	A5  X8
A6 ST4*40=8 	A7  X1			







A1	A2	A3	A4	A5
				
X1	X1	X1	X4	X4
A6 ST4*40=4 				



2



3